

Date: Jan 2016

Address	Classification	Measurements	Notes	Action
228 Hazeltine Dr	Moderate to Significant	2 1/2" displacement	1 panel	replace
212 Hazeltine Dr	Moderate to Significant	2" displacement	2 panels by drain	replace
201 Hazeltine Dr	Moderate to Significant	1 1/2 " displacement		grind
220 Hammock Oak Circle	Small	broken panels	2 panels by drain	replace
155 Red Maple Burl Ct	Minimal	cracked panels no displacement	5 panels by retention pond	watch
Hammock Oak Cir Intersection	Small	2 cracked panels	by fire hydrant	replace
Hammock Oak Cir Intersection	Moderate to Significant	1 1/4" displacement	by fire hydrant	grind
224 Hammock Oak Cir	Small	1" displacement		grind
276 Hazeltine Dr	Small	1" displacement		grind
280 Hazeltine Dr	Moderate to Significant	1 1/2 " displacement w/ cracking	2 panels	replace
285 Hazeltine Dr	Minimal	1/2" displacement		grind
320 Hazeltine Dr	Small	3/4" displacement		grind
376 Hampton Hills Ct	Small	cracked and displaced	1 panel by driveway apron	replace
377 Hampton Hils Ct	Moderate to Significant	2" displacement	2 panles by drain	replace
405 Interlochen Ct	Moderate to Significant	1 1/2" displacement	by lightpole	grind
432 Caddie Dr	Moderate to Significant	1 1/2" displacement	by driveway	grind
432 Caddie Dr	Small	cracked with displacement	4 panels by drain	replace
329 Caddie	Small	cold patch fix	3 panels by by drain	replace
308 Caddie	Small	3/4" displacement		grind
308 Caddie	Minimal	1/2" displacement		grind
597 Quail Lake Dr	Moderate to Significant	2" displacement	1 panel by fire hydrant	replace
324 Quail Hill	Moderate to Significant	2" displacement	2 panels by tree	replace
532 Quail Hill	Moderate to Significant	2" displacement	3 panels by tree	replace
532 Quail Hill	Moderate to Significant	2" displacement	1 panel by driveway apron	replace
103 Birkwood Ct	Small	1" to 1 1/2 displacement	3 panels	grind
111 Brandiwood	Moderate to Significant	2" displacement	2 panels by drain	replace
134 Brandiwood	Small	cracked with displacement	1 panel on Birdiwood side	replace
88 W. Highbanks (School)	Small	1" displacement (bus loop side)	2 panels by drain	replace
85 Columbine Trail	small	unevel panels, prior grinding	5 panels by drain	replace
DeBary Plantation Blvd	Small	cracked no displacement	5 panels West of Plantation Club	watch
DeBary Plantation Blvd	8' panels	cracked and displaced	5 panels between Caddie and Foxhill	replace
DeBary Plantation Blvd	8' panels	cracked by drain	4 panels East of Foxhill	replace
DeBary Plantation Blvd	small	cracked 1/2" displacement	5 panels by LaCreek	grind